WATER QUALITY MEMORANDUM

Utah Coal Regulatory Program

November 7, 2003

TO:	Internal File					
THRU:	Daron R. Haddock, Permit Supervisor					
FROM:	Dana Dean, P.E., Senior Reclamation Hydrologist					
RE:	2003 Third Quarter Water Monitoring, Canyon Fue Mine, C/007/0018, Task ID #1723	l Company, Sc	oldier Canyon			
	submitted for all of the MRP required sites? y sites not monitored and reason why, if known:	YES 🖂	NO 🗌			
2. On what date does the MRP require a five-year resampling of baseline water data. See Technical Directive 004 for baseline resampling requirements. Consider the five-year baseline resubmittal when responding to question one above. Indicate if the MRP does not have such a requirement.						
Resampling due date						
There is no commitment in the MRP to resample for baseline parameters.						
	equired parameters reported for each site? ents, including identity of monitoring site:	YES 🖂	NO 🗌			
	gularities found in the data? ents, including identity of monitoring site:	YES 🗌	NO 🗵			

Page 2 C/007/0018-WQ03-3 Task ID #1723 November 7, 2003

5 .	5. Were DMR forms submitted for all required sites?					
		1 st month, 2 nd month, 3 rd month,	YES \boxtimes	NO NO NO NO		
	All DMRs reported "no flow".					
6.	Were all required DMR parameters reported Comments, including identity of monitoring		YES 🖂	NO 🗌		
	All DMRs reported "no flow".					
7.	Were irregularities found in the DMR data? Comments, including identity of monitoring		YES	NO 🛚		
	All DMRs reported "no flow".					
8. Based on your review, what further actions, if any, do you recommend?						
	No further actions are necessary at this tim	e.				
an O:\	007018.SOL\WATER QUALITY\WQ03-3(1723).DOC					